

## Little Mountain Repeater—Update

The 448.575 repeater has been pretty "deaf" for a couple of years. It has been fully functional, but just didn't hear very well. Multiple things have been tried in the last year, with no success. Another attempt at fixing it was made on the 4th of July 2020, early in the morning, before it got hot.

This time there was success. The duplexer and several small pieces of coax were bypassed. Removing the duplexer required an additional antenna. So, now the 448.575 repeater has two antennas, one for receiving and one for transmitting.

It is operating in a temporary state at the moment and needs some cleanup (coax jumpers and connectors need changing), but it has not worked this well for years. The cleanup will occur in the next few weeks after it has been fully tested out.

Those assisting with the above were:

Mike, KZ7O

Scott, KD7EKO

Todd, KW7TES